



IN. S.P.C. E ZONE NAD '83
NAME: 17041602
N: 519486.7010(m)
E: 64735.9060(m)



CORNER HISTORY: A survey by Wm. B. Laughlin dated 1820 called witness: 14" beech N 88 W 36 links; 14" dogwood S 65 E 20 links per Marion County Atlas. Pg. 12. Old tie cards from Hamilton County acquired called for stone with iron rod by Owens 1966 & 1969. Dug corner in 5-16-1983 48" down, found $\frac{1}{2}$ " steel rod 26" long; but, no stone was found. In 1998 a Hamilton County road construction project destroyed the original monumentation for the section corner. The construction contractor was required by the Hamilton County Surveyor's Office to replace the marker with a Harrison Monument. In August 1998 the Marion County Surveyor's Office discovered the Harrison had been set incorrectly. This information was relayed to the Hamilton County Surveyor's Office. With a combined effort by Hamilton and Marion, the original corner location was found using Marion County GPS coordinates established before construction. Hamilton County then reset the Harrison in the original location. July 1998 Marion County again had reason to question the location. Marion County checked the location with GPS coordinates and found the monument was in the correct location. Re-tied 7-27-01 by Wilcoxen.

REF.	DISTANCE	DESCRIPTION
1.	83.30'	Cut 'x' in S-bolt of aluminum pole base
2.	55.12'	Cut 'x' N-bolt of aluminum pole base
3.	73.59'	PK nail w/brass washer NW PwP#13-174 B 24"up
4.	95.37'	Cut 'x' E-bolt of aluminum pole base
5.	118.87'	Cut 'x' S-bolt of aluminum pole base